


## **SPOIL BOARD CONTENTS**

### Spoil Boards for HD510 & HD520 Includes



### Spoil Boards for HD500 Includes

Part Number

Item Number

Quantity

Part Name




# **SPOIL BOARD** Installation

Assemble the slats by attaching the bolts, washers, and nuts as shown below. Do not overtighten the nut, it will need to be loose to slide into the Aluminum T-Slot Bed on the SHARK CNC.



#### X Assembly

Once all slats are prepared as described, slide them into the Aluminum T-Slot Bed on the SHARK CNC in the orientation shown below



#### Y Assembly

When positioning the slats, insert a pointed bit into your router, then move the router to the front Y-axis travel of the SHARK CNC. Then position the edge of the slat to the tip of the bit. Once all slats are positioned, tighten all bolts to secure the slats to the Aluminum T-Slot Bed.

